

Kensington Police Car Data

Vehicle #	Mileage	Average Monthly Mileage	Hours	Year	Model	Age	Condition
Vehicle #1	63563	174	7197	2006	Ford Crown Victoria	14	Exterior 360 degrees small dents and scratches. Front bumper has a large crack in it. Interior small rips in the seats.
Vehicle #2	59089	920	9721	2013	Ford Explorer	7	Exterior 360 degrees small dents and scratches. Interior small rips in the seats. Having some mechanical issues, noises and electrical, with front drive train and dash board, center console
Vehicle #3	43571	671	7729	2014	Ford Explorer	6	Exterior 360 degrees small dents and scratches. Interior small rips in the seats. Several mechanical issues have been dealt with.
Vehicle #4	64469	421	6393	2009	Ford Crown Victoria	11	Exterior 360 degrees small dents and scratches. Interior small rips in the seats. Condition is fair.
Vehicle #5	58859	unknown	unknown	2005	Ford Explorer	15	Exterior 360 degrees small dents and scratches. Interior small rips in the seats. Several mechanical and is currently at the repair shop.
Vehicle #6	123452	497	509	2010	Ford Crown Victoria	10	Exterior 360 degrees small dents and scratches. Interior small rips in the seats. Mechanically running fair but has noise and rear end problems. Vehicle was almost totaled, severely damaged, while in front of the station where it was hit by another vehicle.
Vehicle #7	62478	340	unknown	2016	Ford Taurus	4	Condition is good. Small amount of damage to front bumper